

Instructions

Rack Mount Bushings - Bump Steer Correction

Application: Ford Mustang 1985 - 2004


The servicing of the steering rack should be carried out by a qualified technician with the aid of the Factory service manual.

Note image below - place bushing offset downwards at 6 o'clock
Re-use the OE inner steel tube.

When re-positioning rack and tightening rack bolts, loosen the pinion/coupling bolts to remove any potential binding.
Re-tighten afterwards.

A wheel-alignment must be carried out after install

Position bushing offset downwards
at 6 o'clock - this will lift the rack.



N.B: It is recommended that a licenced workshop or tradesperson carry out the above procedure and that workshop manual and relevant safety procedures are followed in addition to the above.